

LPA58 Product Revisions

Released: July 11, 2019

Firmware: **LPA58_v0.9.59** Software: **WireScan3 v3.7.1.0**

Framework: .NET 4.0 Windows: XP, W7, W8, W10

Updates:

- Added support for new hardware with independent high and low input pins to accommodate new 485 cable and reduced input pins.
- Added support for 485 communications
- Firmware can still be used on RS232 hardware
- AutoGen in Bootloader updated to give error response instead of ignore response when a message is not correct

Released: June 18, 2018

Firmware: **LPA58_v0.9.56** Software: **WireScan3 v3.7.0.11**

Framework: .NET 4.0 Windows: XP, W7, W8, W10

Updates:

- Multiple updates and fixes.
- AutoGen updated.
- Improved serial port data receive handler.

Released: October 17, 2017

Firmware: **LPA58_v0.9.52** Software: **WireScan3 v3.7.0.2**

Framework: .NET 4.0 Windows: XP, W7, W8, W10

Updates:

- Big Seal Mode added.
- Removed minimum number of line scans limitation.
- Updated protocol to 5.

Released: August 22, 2017

Firmware: **LPA58_v0.9.47** Software: **WireScan3 v3.6.9.3**

Framework: .NET 4.0 Windows: XP, W7, W8, W10

Updates:

- Fixed Wire position and Seal position Trend label.
- Added pointer to Wire position actual value on wire image.

Released: May 24, 2017

Firmware: **LPA58_v0.9.47** Software: **WireScan3 v3.6.9.2**

Framework: .NET 4.0 Windows: XP, W7, W8, W10

Updates:

- Fixed issue with learning first piece, half image.
- Fixed multiple Learn button pushes and cascading message box prompts.
- Fixed firing pulse issue with debounce.

Released: April 17, 2017

NOTE:

OES is committed to supporting our customers by continuously improving our products with new features and enhancements to advance the product performance in the production environment. These new product versions are made available to our customers following extensive testing and validation to ensure reliable performance. Since we cannot replicate the production environment it is recommended that the customer validate the new version for performance specific to your machine, process, and production environment to ensure this new release meets performance expectation.





TECHNOLOGIES

Firmware: **LPA58_v0.9.42**

Framework: .NET 4.0

Updates: - Initial release

Software: **WireScan3 v3.6.9.1**

Windows: XP, W7, W8, W10



NOTE:

OES is committed to supporting our customers by continuously improving our products with new features and enhancements to advance the product performance in the production environment. These new product versions are made available to our customers following extensive testing and validation to ensure reliable performance. Since we cannot replicate the production environment it is recommended that the customer validate the new version for performance specific to your machine, process, and production environment to ensure this new release meets performance expectation.

www.oestechnologies.com

WIREScan™

Product specifications and related information subject to change without notice.

*The information in this file is to be considered '**CONFIDENTIAL**' and subject to the relevant terms and conditions of all agreements in place between OES, Inc. and the recipient's company. If you are not the intended recipient of this information, you are hereby notified that any use or disclosure of any information in this file is prohibited.*